



TSB-274

Crank to Flywheel Spacer

This vehicle has a flywheel spacer fitted from the factory, as pictured below for example. This spacer **MUST** be re-fitted when installing your new clutch kit. Failure to do so can cause spline engagement and ring gear/ starter motor engagement issues.







LEADING BRANDS





